Lynn Allen's Tips and Tricks for AutoCAD 2012

AutoCAD[°] 2012

Autodesk[®]

Inter

User Interface


The UI in AutoCAD 2012 software just gets easier and easier to work with.

AutoComplete

For those of you who like to key in commands—save time with AutoComplete! As you key in commands, AutoCAD automatically completes the entry. If you pause, a list of all possible commands and system variables displays for easy selection.

Y 🗄	AR (ARRAY)
1	[®] ARC
	ARCHIVE
<u> </u>	4 ARCTEXT
	AREA
Command	ARM (ACTUSERMESSAGE)
Command	ARO (DBCONNECT)
Command:	AR
13.8360, 1.90	09 , 0.0000 🛛 💠 🕮 🛄 上


Customize AutoComplete from the command line right click menu (even control the delay response time).



You'll also notice that the command history is now displayed with a grey background color. This can be modified in Options (Display Tab ->Colors...).

Changing the Ribbon

For those of you who would like the Ribbon to take up less room you'll appreciate the pull-down menu that was added to the ribbon cycle button. The Minimize to Panel Buttons option displays large icons for each panel. The panel will expand when you hover over the button.



In-Canvas Viewport Control

It's easier than ever to set up or modify your viewports, 2D and 3D views and visual styles directly from the drawing window (big time saver!)

NOTE Control the display of these in-canvas viewport controls from the 3D Modeling tab of Options.



TIP Double click on the – to quickly display 4 viewports or the previously specified viewport configuration.

Drawing Window

AutoCAD displays a dark gray background in modelspace (by default). The Display tab in OPTIONS lets you easily modify the color.

The grid has been modified to resemble graph paper (horizontal and vertical gridlines). You'll see red and green lines extending from the UCS to indicate the X and Y axes when the grid is toggled on.

Quick Access Toolbar

The Workspace menu and SAVEAS have been added to the Quick Access Toolbar.

TIP Put the Layer drop-down list on the Quick Access Toolbar for speedy access at all times! A simple right click on the layer drop down list allows you to easily add it.

Unsaved Layer State	▼ Text ✓ [●] Leader ▼	Insert
💡 🔅 🔂 🔐 🔳 o	Add to Quick Access Toolbar	
Layers 👻	Show Tabs	•
	Show Panels	•

Customizing the Ribbon


Enhancements allow you to include Fold panels. As you change the size of your AutoCAD window or add and remove panels from a tab, Fold panels resize horizontally to fill the available space. You can specify a default, maximum and minimum button size for each panel in the CUI.

Navigation

nter

The Navigation bar replaces the navigation tools that were previously available on the Status bar. This bar resides on the right side of the screen by default and includes Autodesk[®] SteeringWheels[®], ViewCube[®], ShowMotion[®], Pan, Zoom and Orbit tools.

The Navigation bar also includes support for 3D Connexion devices when the 3D Connexion system driver is present.



M

Ŷ

The ViewCube supports the 2D Wireframe visual style (you might find the clockwise and counter-clockwise controls useful for rotating the viewpoint in the 2D plane).

UCS Icon

Each axis has its own color: X for red. Y for green and Z for blue.




Object Selection and Creation Tools

Implied Selection

When selecting objects (outside of a command) you'll find the additional options of Wpolygon, Cpolygon and Fence appear.

Can't decide whether you prefer pick and drag or picking two points to define a window? The new PICKDRAG setting of 2 combines both options.

PICKAUTO set to 2 allows you to start a window even when picking on an object (for those crowded drawings). This only works outside of a command.




TIP Now SNAPMODE temporarily turns off when selecting objects.

Select Similar

The Select Similar tool allows you to quickly select objects of the same type and properties (much faster than Quick Select). Find this tool in the right-click menu when one or more objects are selected.

Use the Settings option to specify which properties to filter (only available when vou enter SELECTSIMILAR from the command line).



TIP You can select more than one object to match with Select Similar. For example, if the Layer filter is enabled and you select a circle and a line that reside on two different layers, AutoCAD will find all of the objects that match the circle AND all of the objects that match the line.

Creation Tools

Object Selection and


Object Visibility

Control object visibility independent from layer visibility! The Isolate Objects tool (found in the right-click menu) displays just the objects selected (everything else is hidden). This makes it easier to work within complicated drawings.

You can use the Hide Objects tool (also found in the right click menu) to hide the objects selected.

Quickly restore the hidden objects with the End Object Isolation tool.

NOTE Use the OBJECTISOLATION-MODE (yikes!) system variable to control whether object isolation persists between drawing sessions.



The lightbulb icon in the lower right cor-

ner of the status bar indicates whether

object isolation is active in the drawing.

TIP These tools can be VERY valuable

For you programmers: the system vari-

able PICKADD has a default value of 2.

The objects selected with the SELECT

command will now remain in a "pick-


first" state after exiting the command.

when working in 3D!

PICKADD

Easily select overlapping objects with the Selection Cycling tool (controlled on the status bar). When you select an object that overlaps other objects, AutoCAD displays a list of all the overlapping objects. Objects highlight as you move through the list.

TIP Selection Cycling can also be very helpful when working in 3D.



Add Selected

Need to draw an object with the same type and properties of an existing one? Use the Add Selected tool to get the job done in no time! For example, select a polyline, pick Add Selected from the right click menu and AutoCAD is ready to create another polyline with the same properties. This is a HUGE timesaver!

TIP Very helpful when working on other people's drawings! For example: use Add Selected to quickly add in another dimension with the exact same style and settings.

Autodesk Content Explorer




Autodesk Content Explorer

Speedy searches for all types of content including blocks, attributes, layers, styles, etc. Found in the Plug-ins ribbon tab, Content Explorer can search through thousands of files almost instantaneously including Autodesk® Seek web service (much faster than Design Center!)

Filter content and switch between thumbnail and detail views. Drag content into your current drawing or open the source file from Content Explorer.

Use Add Network Content to specify computer name or IP address of the network computers.

TIP Search Autodesk Seek to easily add online content from a variety of manufacturers.



Drag and drop local folders for searching from Windows Explorer or use the Add Watched folder option.



Install the Autodesk Content Service (found on the AutoCAD 2012 installer) on network computers to add watched folders from other computers.


NOTE You can only add shared folders.

Editing Tools


Multifunctional Grips

In AutoCAD 2012 multifunctional Grips have been added to many objects!


Polylines have extra grips to make editing much easier. Secondary grips are located at the midpoint of each segment. Hovering over a grip provides several valuable editing options such as stretch, add or remove vertex and Convert to Arc/Line.



Look for these powerful grips in lines, arcs, elliptical arcs, dimensions and mleaders. 3d faces, edges and vertices also have them. Just hover over a grip to access numerous relevant options.



Editing Tools



TIP Multifunctional grips are even more powerful when dynamic input is on.

Nudge!

Have you ever wanted to move objects over by just a few pixels? Use Ctrl and your arrow keys!

Osnap Enhancements

Added flexibility helps AutoCAD find object snap points to make objects tangent or perpendicular. Choose from multiple snap points based on the location of the cursor.

Copy Improvements

You'll find a new Array option in the Copy command. It lets you create a linear, non-associative array on the fly!

Groups

Groups are in many a CAD guru's bag of tricks. Now you'll find easy access to groups on the Home tab of the ribbon.




A group is a saved set of objects that you can edit together or separately when needed. Groups make it easy to manipulate a group of objects as a unit.

TIP Use Shift+Control+A to quickly turn Grips on and off.

Fillet and Chamfer

New previews display when passing the cursor over the second object in the Fillet/Chamfer commands. Confirm and change the radius or distance before completing the command!



Express Tools become "Real" commands

The NCOPY Express Tool is now a core AutoCAD command. Copy nested objects from Xrefs, blocks and DGN underlays (no need to explode or bind!).

Use the Delete Duplicates tool (OVERKILL Express Tool) to clean up your drawing and remove duplicate geometry.



Control OVERKILL settings in the dialog box. Specify which object properties to ignore along with whether or not to optimize polyline segments and/or combine co-linear objects. The tolerance value controls the precision by which OVERKILL will operate.


JOIN Command

You can join lines, arc and polylines to 3D polylines or splines as long as they are contiguous. (3D polyline or spline). You can also join a helix to a spline.

TIP Join now supports standard selection methods (such as crossing) or picking objects in any order!

New Blend Tool

Use the Blend command to create spline objects between two objects (Modify panel of the Home ribbon tab).




13

Associative Arrays

An associative array treats the entire array as a single array object (much like a block). This makes it easy to edit the properties of the array after the fact. There are three types of Associative arrays: rectangular, polar and the new path option.

2D Associative Arrays


The new visual preview makes it easier than ever to get your array right the first time.




It's easy to manipulate with multifunctional grips or the Properties palette. The contextual ribbon tab and right click menu also makes it easy to edit an associative array. The contextual ribbon tab and right click menu makes it easy to edit an array.

Individual items in an array can be selected and edited by using the Ctrl Key. Use the new Replace item tool to replace selected instances with other objects.

TIP The Reset tool returns the items to their default size and position.



Change the appearance of all the arrayed objects with the Edit Source tool.



Path Arrays

Distribute items evenly along a specified path. The Measure option is used to specify a distance between the items. Use Divide to specify the number of items. (AutoCAD will space them evenly along the path.) If the path is modified the arrayed objects will follow!

A valid path option is a line, polyline, 3D polyline, spline, helix arc, circle or ellipse. Specify whether the arrayed objects should maintain the starting orientation or adjust to remain parallel to the path.

TIP Use base point to control the position of the arrayed items relative to the path.

BONUS TIP Explode an array to remove the associativity.

3D Associative Array

3D Associative Arrays are also very powerful. Indicate the number of levels (the number of items needed in the Z direction) and specify the distance between levels.



NOTE A distance of 0 between levels would create all rows at the same elevation.

Associative Array

elpful Tim

Helpful Time Savers

External References

Passing the cursor over the edge of an attached image, DWF or PDF will display a selection preview frame (even when frames are turned off). You'll also find this when you pass your cursor over geometry inside of attached DWF, PDF, DGN or DWG files.

NOTE The new system variable FRAMESELECTION controls this behavior.

The External References palette includes an option to detach data extraction tables from a drawing. You'll also find that the corresponding reference highlights in the External References palette when selected.

TIP You can easily fade reference files from the Reference panel on the Insert tab.


Attach Clip Adju	Underla	ay Layers s vary* •	
Attach Chp Aujo	P Snap to	Underlays	ON •
M Edit Reference			
Xref fading	[70	
-[22 F	Reference		ы

Scale Lists

Create a Default Scale List (Options command, User Preferences tab) that automatically displays across all of your drawings.

Text Alignment in Linetypes

The option of "U" (for upright) can be added to your linetypes to maintain linetype readability in any orientation.



Missing SHX and Font Files

You can ignore missing SHX files when opening a drawing without specifying a replacement (although text using the missing SHX files will not be displayed).

Annotation

Mtext background mask now remembers the last used fill color and offset. (No more defaulting to red and 1.5!)

You can now change the gap around Mleader text in a text frame. You can also extend the leader line all the way to the text (rather than ending at the bounding box).



TIP Remove Style Overrides has been added to the right click menu when you select a dimension.

Transparency

You can assign transparency to objects and layers much like any other property! Set the transparency to a value between 0 and 90. 0 indicates no transparency while 90 indicates high transparency.



You'll find the Transparency property in all the Layer Dialogs and you can even assign Transparency per viewport.


		nt layer: 0	**	1															Se	arch for	aye G
X	15	Name	0.	Fr	. L.,	Col	. U	inety	Linew	Transparency	Plot	P.,	N.	V., 1	VP	VP Lin.	VPI	lin_	VP Transparency	VP P	Des
	0	SIN W	8	10	of the		. 0	ontin.	- De.,	50	Colo	0	5	F	2_	Contin.	-	De.	50	Colo	
	0	ALI PLA.	8	*	ď		0	nin.	- be.,	0	Colo_	60	12	ES 📕	1_	Contin.	_	De_	0	Colo_	
	10	ALIRD -	8	**	ar		- 0	ontin.	- De.	0	Colo	0	п.	۵ E	2_	Contin.	-	De_	0	Colc_	
	0	ALI TUB	8	106	ď		3 6	ontin.	- De.	70	Colo	9	63	C. 🛙	13	Contin.	-	De.	70	Colo_	
81	0	BJ48 - R	8	10	đ	1	0	ontin.	- De.,	50	Colo	0	5	F5	1.	Contin.	-	De_	50	Colo	
SI.	0	BJ48 - R.,	8	305	ď	1 1	0	ontin.	- De.	0	Colo	63	63	65 E	1_	Contin.	-	De.	0	Colc_	
	-	8)48 - R.,	8	300	ar		- 0	ontin.	- De.	70	Colc	0	5	65 E	1_	Contin.	-	De_	70	Colc	
88	0	8/48 - R.,	8	105	ď	11	0 0	ontin.	- De.	50	Colo.	0	53	C3 [1 50	Contin.	-	De.	50	Colo	
	0	BJ48 - R.,	8	10	all a		. 0	ontin.	- De.,	0	Colo	63	г.	r.	f	Contin.	-	De.	0	Colo	
	0	8/48 - R_	8	-106	ď		4 0	ontin.	- De	70	Cole_	60	63	65 🖥	84	Contin.	-	De_	70	Cole_	
1	10					-															

You can also set transparency per object (which will override the layer transparency setting). Transparency can be easily found in Properties or on the Home tab.

TIP The system variable CETRANSPAR-ENCY can be used to set the transparency property for new objects.

NOTE SETBYLAYER, Quick Select, Filter and MATCHPROP now include Transparency as an option.

You can temporarily turn off transparency, much like lineweights, from the status bar (this does not affect plotting).




TIP Transparency works great with solid hatches!


NOTE By default Transparency is turned off for plotting (since it has to rasterize the drawing which slows down plotting). Don't forget to turn it on if you want your transparencies to plot!

Spline Enhancements

AutoCAD lets you define a spline using fit point or control vertices (CV).



When drawing a fit spline, you can specify start and end tangencies, tolerance (how close the spline is to the fit point) and knot parameterization (which controls the shape of the curve as it passes through the fit point)



You can control the Degree of a CV spline (the number of bends—from 1 to 3—that the spline can take overall).

Use the intuitive grip menu to further control splines.

Use a CV spline if you plan on creating 3D NURBS surfaces for best results.

SPLINEDIT has been updated to include more Edit Vertex options like add kinks or elevate order.

AutoCAD 2012 supports periodic splines with C2 continuity. The knot parameterization property of a spline is no longer read-only.

TIP You can now use the Extend command to extend spline objects!

Layers Improvement

Use the right click menu in the Layer Properties Manager to quickly freeze specified layers in all viewports except the current one (handy!)

	New Layer VP Frozen in All Viewports	_	F	😔 📭	- 125	Continu	_
0	VP Freeze Layer	►		In All Vie	ewports Excep	ot Current)
1	VP Thaw Layer in All Viewports			In All Vie	ewports		Ϊ

16

Helpful Time Save



. DDE	18.0	÷ • • • • [Dratting & An	notation		AutoCAD	2012 Dra	awing2.du	9	Type a keyword or p	insse	63 .4	Sign In	- 53		2
Home	Inert	Annotate Par	nametric View	Manage	Output	t Plug-ins	Online	Express	Tools	Hatch Creation	•••					
Ack Points	SOLID	ANGLE	ANSED:	ANSID2		Auttern Use Currer None	nt		Angle	latch Transparency	0	Set Origin	Associative	Amoterive	Match	Close Hatch Creation
Boundaries +		p	Pattern			-		Prope	rties =			Origin -		Options +	,	Close

The context sensitive Hatch Creation tab does a great job of making hatching much easier and more intuitive. As soon as you execute the Hatch command you will be asked for an internal point. (What? No hatch dialog box?) Just passing your cursor over an eligible area shows you what the hatch will look like. Use the Hatch Creation tab to make changes dynamically.

NOTE Even though it looks as though you created separate hatches as you clicked—they won't actually be separate unless you have "Create Separate Hatches" selected (found under Options).

Grips

The Hatch Grip functionality is amazing. The new center grip allows direct manipulation of hatch objects. Hover over the grip to stretch, move, or change the origin, angle or scale.

TIP You'll also find that it is easy to manipulate non-associative hatch patterns with grips!

ngle:
le between:
-
-

Hatch Laver

We often want our hatches to all reside on a specific layer. Now you can set a default layer for hatches that overrides the current layer.

3D Tips

Send Hatches to Back

Use the HATCHTOBACK command to move hatches underneath all other objects. This command is located on the Modify panel of the Home tab.


Background Color

Hatches now support background color-this adds the effect of layered hatches within one object.



UCS Enhancements

Directly manipulate the UCS icon to easily change the UCS using multifunctional grips. Easily move and align the origin with objects (including curved surfaces and solids). Select the UCS icon and choose from the various menus that appear as you hover over the grips.



NOTE UCS icon selectability can be controlled in the UCS dialog box (Coordinates panel, View ribbon tab in the 3D Modeling workspace).




TIP The UCS icon also displays a dynamic preview in the UCS command.

3D Object Snaps

A set of 3D Object snaps are in AutoCAD along with a button on the status bar to turn them on and off.

TIP A new 3D Autosnap control has been added in Options so you can distinguish between 2D and 3D Autosnaps with different colors.




Selecting edges, faces and vertices

In the past it has been tricky selecting between an edge, face or vertex. The Subobject panel on the Home tab makes quick work of this now! These options are also available from the right click menu when no objects are selected.

No Filter	Move
No F	ilter
Verte	ex
Edge	
Face	
G Solid	History


The 3D Gizmo

A 3D Scale gizmo has been added to 3D Move and 3D Rotate for more 3D functionality.



If you are using a 3D visual style the gizmo will display when an object is selected. The Selection panel on the Home tab makes it easy to change from one gizmo mode to another.

You can go directly to a specific gizmo with the 3DMOVE, 3DROTATE and 3DSCALE commands. You'll find that the gizmos go directly to the center of the selection set. (Saving you that extra step.)



A right click on a gizmo lets you modify the gizmo's behavior. Here you can constrain to a different axis or plane, relocate it and realign it.

3D

23

Solid Modeling

Updates to EXTRUDE, LOFT, REVOLVE and SWEEP allow you to select an edge or face for using as a profile or curve to create a new surface or solid.

NOTE You are no longer limited to using planar curves!

Fillet Edge and Chamfer Edge

Found in the Solid tab, the Fillet Edge and Chamfer Edge tools provide a dynamic preview and support direct manipulation by pulling on the attached grip.

New Chain and Loop Selections:

Selecting contiguous edges and curves just got so much easier!

SURFPATCH, SURFBLEND, MESHCAP and FILLETEDGE now detect contiguous edges with a solid or mesh object (or within/between surfaces).

A new Loop option (much like a closed chain) can be found in FILLETEDGE and CHAMFEREDGE.

Offset Edge

Create an offset curve from a planar face on a 3D surface or solid. Offset to the inside or outside using your cursor to produce a polyline or spline and indicate sharp or rounded corners.


Follow this up with Presspull or Extrude to easily add or remove the bounded area from a solid.



NOTE Now Presspull repeats so you can press and pull multiple times in a single operation.

Autodesk Inventor Fusion

Use the very cool Autodesk® Inventor® Fusion technology to easily edit and validate models from almost any source. The super friendly and intuitive direct manipulation capabilities provides direct modeling for speedy design changes in 3D.




Without exiting AutoCAD, you can launch Inventor Fusion, use it to modify a 3D model and then continue working on the modified objects in AutoCAD.

NOTE You must install Autodesk Inventor Fusion 2012 to use it.

After installing—it can be found in the Plug-Ins tab on the Ribbon . When you select a surface or solid in AutoCAD, the Edit in Fusion tool is automatically displayed at the right end of the contextsensitive tab.

In Fusion you can zoom, pan, and orbit to navigate around your model similar to AutoCAD. You'll even find the familiar Navigation bar and ViewCube.



25


The power in Fusion is the direct editing capabilities. Intuitively edit and validate models from almost any source. Click on a model edge or face to select it for editing. Press the Ctrl key to select multiple objects (just as you would expect).

The ribbon interface as well as contextsensitive right-click options provides easy access to relevant editing tools.

With Inventor Fusion you can quickly and easily insert standard, counter bore or

countersink holes, add or modify fillets and chamfers along with many other 3D capabilities. Fusion is very intuitive and easy to use (and addicting)!

When you are finished editing your model in Inventor Fusion—return to AutoCAD by selecting the Return to AutoCAD tool.



Surface Modeling

A			• - [@	3D Mod	eling		Aut	ICAD 2	012 Drawi	enb.ton	Type a keywor	d or phrase	8	H 1 50	nin	- 10 -	-	22
Hor	ne Solid	Surface	Mesh	Rende	r Paramet	tric Inse	rt An	notate	View M	lanage Out	put Plug-in	s Onlin	e Expre	ns Tools	••			
 Network Loft Sweep 	 Planar Extrude Revolve 	Blend	Patch	Offset		41	Fillet	Trim	Unorim	CV Edit Bar	Convert to NURBS	Show CV	20 10 10 10 10 10 10 10 10 10 10 10 10 10	Soline CV	210	Auto Trim	Analysis Options	
		Cn	este					Edit	*		Control Ver	tices		Cun	* 25	Project Geometry	Analy	55

Surface modeling has seen some dramatic improvements. A type of surface called a Procedural surface, is actually associated with its defining geometry. This makes it easier than ever to digitally sculpt your designs in 3D.

NOTE NURBS surfaces are not associative (and have no history). They have control vertices that allow you to sculpt your designs.

The Surface tab provides easy access to the surface modeling tools.

Surface Creation Tools

There are three analytic surface types in AutoCAD 2012: Blend, Patch and Network

The new SURFBLEND command can be used to create a continuous blend between two existing surfaces.




SURFPATCH lets you patch an open, closed-edge object.




Autodesk Inventor Fusion

SURFNETWORK is used to create a surface through a set of curves or between the edges of other surfaces and solids.



NOTE You can even choose a set of curves that are not connected to one another!

SURFOFFSET can be used to create a new surface by offsetting an existing one.



TIP Turn on Surface Associativity when creating surfaces so the surfaces can be driven by their defining geometry.

Surface Editing Tools


Use the SURFFILLET tool to create a fillet between two surface edges.

The very powerful SURFTRIM tool can be used to create complex edges and holes.

NOTE Use the UNTRIM command to undo a trimmed surface.

SURFEXTEND is used to extend a surface by selecting an edge.

SURFSCULPT creates a solid object based on the enclosed volume of more than two intersecting surfaces.



In the Project Geometry panel you'll find tools that let you project geometry on top of surfaces. AutoTrim is used to specify if you want surfaces automatically trimmed after a projection.



You can convert a surface or solid to a NURBS surface with the Convert to NURBS tool. Use Show CV to display the vertices for editing with the gizmo along with the other tools on the Control Vertices panel.

NOTE You'll lose any associativity when you convert to NURBS.


Analysis Tools

A set of analysis tools have been added into AutoCAD to help you validate the continuity, curvature and draft angles of surfaces.

Zebra: Maps stripes onto surfaces and meshes for analysis. The more the stripes line up, the higher the continuity between surfaces.

Curvature: Displays a color gradient that indicates high and low areas of curvature along with unacceptable sudden changes such as bumps, dents and ripples.

Draft Angle: Displays a color gradient indicating if there is adequate draft angle between the part and the mold.



Surface Modeling

Model Documentation

Model Documentation

3D Model Import

So many file formats—so little time! Now you can import a much wider variety of file formats including CATIA, NX, Pro/Engineer, Rhino and SolidWorks.

The data is translated to native AutoCAD geometry and inserted into the drawing as blocks. Parts and assemblies are preserved as nested blocks. And of course you can edit the objects. Just explode it first!


Model Documentation

It's never been easier to go from your 3D models to 2D documentation. You'll even find that if you modify the 3D model—the 2D documentation will update as well!

The new model documentation commands are found in the Drawing Views panel of the Annotate ribbon tab.

Type a keyword or ph	90e - 98 .0	Sign In 🚽 🔟	? ·	
Wipeout Revision Cloud	Add Current Scale	الله Scale List 양 Add/Delete Scales 같은 Sync Scale Positions	Base	E Projected View E Edit View D Update View •
Markup	Annota	ation Scaling	D	rawing Views

Start with Base View to automatically display a scaled preview of the model attached to the cursor. Specify options such as type, orientation and scale.



Create projected views from the Base view (as long as the Type option was set to Base and Projected) by dragging the cursor to the desired location. AutoCAD automatically creates the appropriate view.

Modify properties for a selected drawing view using the Properties palette.



Easily modify drawing views from the contextual ribbon tab by double-clicking on a view.

NOTE Projected views become the child in a parent/child relationship and inherit the parent properties and edits.


TIP Use the multifunctional grip at the center of each drawing view to stretch or rotate a view—or break and repair alignment.

AutoCAD clues you in when the source model changes (making your drawing views out of date).

1	I A Model Has Changed X	`
	One or more drawing views are no longer up to date. Update all views on this layout.	
PE	R 💵 🔲 🗛 🌣 🗗 🖷 💽 🕞 🗖	

Applying Standards

Specify drafting standards for new drawing views in the Drafting Standard dialog (lower right corner of the Drawing Views ribbon panel).



TIP Use the Export Layout tool to export your finished Drawing views to model space (found in the right click menu of the layout tab).

You can attach and display point clouds created from 3D Scanning devices.



Point Cloud 🔻

Point Clouds are attached much like other reference files and can contain up to 2 billion points!

and Indel Astaland Pasers	AutoCAD X11 Deno/DissurgetMandshrypeg	Dovse.		
Pavies	Patripa	Scale		
	Fulpeth ·	Spacily on-scream		
		1 0000		
	insection point	Rotation		
Preview not available	Specify on acreen	Deputy on screen		
	x 0.000	Angle: 0		
	Y 0.000			
	Z 0.0000	Use peopraphic location		

TIP You'll probably want to lock down the point clouds so the points don't move.

You can create geometry from the point cloud data by snapping to points (the Node object snap). Adjust the point density in the Density slider bar for better performance.




NOTE AutoCAD 2012 has an improved indexing algorithm for optimized viewing when changing zoom levels.

Materials

The Autodesk Materials Library is now available online (download and install when needed). You'll also find that it is overall easier to use and better organized.

The Materials Browser makes it easy to browse and search from over a thousand materials in the Autodesk Materials Library. The Materials Browser can be found on the Render tab of the 3D Workspaces.



Easily create, categorize and open your own materials library from the Materials Browser as well. Use the robust search feature to find specific materials and then add them to the current drawing.

You can easily edit the materials in the updated Materials Editor. Materials that have been placed in the drawing will dynamically update.

	♂ Create Material Options Options · Options · · Options ·							
	Name Stone - Blue							
	▼ Generic							
	Color RGB 0 0 0							
	Image							
	Stone_2.png							
	Image Fade 100							
	Glossiness 50 -							
	Highlights Non-Metallic -							
	Reflectivity							
litor	Transparency							
Is Ed	▶ Cutouts							
Materials Editor	Self Illumination							
W Na	► 🗸 Bump							

Model Documentation

Added Extras

Added Extras

Autodesk[®] Exchange for AutoCAD

Get up to date information, videos, plugins and help content delivered to your AutoCAD workspace from the Autodesk Exchange. Displayed when you start AutoCAD 2012—you can also access it from the upper right corner of the AutoCAD window.



Autodesk Seek

Don't miss out on the great content available (for free!) up on Autodesk Seek service. Easily get to Autodesk Seek from the Content panel on the Insert tab or from inside of Design Center.

Autodesk Seek

Search All File Types	garag		IY BIM?		Learn More
Filter		Results by: Product Manufacturer		Email a	earch results
Category		<< < New showing 1-20 of 46 entries > >> View Options	2 IEI 501	ty Relevance	
Automatic Door Controls and(1) Colleg Doors (1) Fire Shutters (1) More >>		Design 301 Sectional Overhead Steel Garage Doors, 60" Height, 96" or 192" Width Newslearer Carage Heese Deer Company	22 HTA 23 HDF	22 DWG	22 DWP
Content Source	B	a.			
Manufacturer (45)		Design 303 Sectional Overhead Steel Garage Doors, 96" Height, 96" or 192" Width	Land	4 0W9	₩40WF
Manufacturers	E	Manufacturer Carriege House Door Company	1 PDF	4 D.T.	📬 4 ZP
Amair Garage Doors (13) 87 - Glass Garage Doors & E., (3)		er.			

Nearly 1000 manufacturers and 35,000 products are available on Autodesk Seek (over 100,000 DWG files).

You can also share your designs by uploading them directly from AutoCAD.



Raster Files

Son in | Join Now! | Demo | FAD | Support Forum

AutoCAD 2012 accepts more file formats for attaching: DDS, DOQ,ECW,HDR, JPEG2000, MrSID, NTF, OpenEXR, and PSD.

NOTE All images from AutoCAD[®] Raster Design are automatically displayed.

Migration

Tool Palettes (including groups) and Materials Libraries migrate from previous releases (with better results). You can also easily return to the default settings with the new Reset tool found in the Windows Start menu.

Multiple search paths for plot files

You can now specify multiple folders for PC3, PMP, CBT and STB files in Options.

DGN[™] Support

Complex linetypes are now maintained! To ensure that custom linetypes are displayed, copy the corresponding .rsc files to the support path or add the RSC file path to the search path in AutoCAD in the Options dialog box (Files tab, Support File Search Path).

DWG Convert

Batch convert drawing files to Release 14, 2000, 2004, 2007 and 2010 with the DWG Convert tool (DWGCONVERT). You can save the lists for future use and specify options such as purging the drawings.



TIP Use DWGCONVERT to quickly replace page setups in multiple drawings!

 $\mathsf{Autodesk}^{\circledast}$ Vault software now supports the Sheet Set Manager.

Autodesk Vault is a great means of managing all of your design data. Users check in and out drawing files from Vault, which maintains revision information. Vault is also a powerful data reuse and collaboration tool (free for subscription members!).

The right click menu in the Sheet Set Manager now includes vault options to log in and out of Vault. AutoCAD WS

AutoCAD WS

Have you tried AutoCAD[®] WS web service yet? AutoCAD WS lets you view, edit and share drawings through the web or mobile device (take your drawings on the road!).


AutoCAD 2012 makes it easier than ever to upload your drawings to an AutoCAD WS server. Set up an automatic upload to ensure the most recent file is always posted (Manage Uploads tool).

TIP You can also upload other types of files such as images, documents and spreadsheets (Upload Multiple Files tool).

Manage U	ploads				
Manage file uploads to th	e web server				
▶ Resume all uploads	 Stop all uplos 	ads			
Name	Size	Path	Туре	Last Upload	Status
📝 🤵 R00-D3.dwg	965 KB	C:\Users\hewett	AutoCAD Drawing	3/14/2011 11:11:	Uploading (85%
📝 🚍 R00-A1.dwg	251 KB	C:\Users\hewett	AutoCAD Drawing	3/14/2011 11:12:	Uploaded
V 📑 R00-A3.dwg	1258 KB	C:\Users\hewett	AutoCAD Drawing	3/14/2011 11:11:	Uploading (30%
V 📑 R00-D1.dwg	673 KB	C:\Users\hewett	AutoCAD Drawing	3/14/2011 11:09:	Uploading
🔽 🚍 R00-A10.dwg	1072 KB	C:\Users\hewett	AutoCAD Drawing	3/14/2011 11:10:	Uploading (100
PLAN LIST.dwg	285 KB	0.111	AutoCAD Drawing	3/14/2011 11:11:	Uploading

Use the Open Online tool to access and edit the drawing online in AutoCAD WS.

View all of your online drawings and folders with the Online Drawings tool.



Use the Timeline tool for a detailed design history.



But wait—it gets even better! Use the Share Drawing tool to collaborate with others (even if they don't have AutoCAD installed). AutoCAD WS will automatically notify collaborators with an email invitation.

TIP You can also use the Get Link tool to embed a link to a drawing in web pages and documents.

Give AutoCAD WS a try—did I mention it's free*?



Download the free* app for iOS mobile devices at the App Store. Also available for the Android.

*Free products and services are subject to the terms and conditions of the end-user license agreement that accompanies them.

Autodesk Design Suite 2012 (Standard)

Enhance the power of AutoCAD with easy-to-use visual communication solutions. Autodesk Design Suite helps designers work more creatively, rapidly evaluate designs in context and effectively communicate and sell ideas. Autodesk Design Suite Standard contains AutoCAD[®], Autodesk[®] SketchBook[®] Designer, Autodesk[®] Showcase[®], and Autodesk[®] Mudbox[™] software. The Premium version of the suite adds Autodesk[®] 3ds Max[®] Design. The Ultimate version of the suite also adds Autodesk[®] Alias[®] Design.



AutoCAD WS

Autodesk SketchBook Designer

Sketch conceptual designs directly into AutoCAD. Tap into a unique hybrid paint and vector workflow and explore many different design concepts. Communicate your ideas graphically!

- Illustrate on a blank screen
- Design conceptually with pencil and paper-like sketching
- Combine and compose images
- Create graphic designs and communications



Autodesk Showcase

Quickly and easily transform your AutoCAD designs into compelling imagery, movies, and interactive presentations for design reviews and sales pitches. Evaluate design variations and accelerate feedback by reducing the need for physical prototypes and long rendering times.

- Accelerate the path to new business by selling your ideas more effectively
- Reduce the time, expense, and expertise required to prepare visualizations
- Facilitate informed decision making by viewing design options in context and in detail



Image courtesy of Hurni Engineering, Jean-Marc Benoit

Autodesk Mudbox

Refine your models with Autodesk Mudbox. Its powerful textured painting and digital sculpting toolset lets you finesse the details of your ultra-realistic models.

- Get fast, smooth, and accurate results with a world-class 3D sculpting toolset
- Paint directly onto high-resolution 3D models and see results immediately
- Create accurate normal, displacement, and ambient occlusion maps with texture baking



Image courtesy of Benjamin Brosdau

Autodesk 3ds Max Design (available in Premium)

Perform daylight analysis and create cinematic-quality 3D visuals with the animation, character, effects, and point-and-shoot rendering and lighting analysis tools. Convey the story behind your design for design reviews, marketing materials, or public outreach—before it's real.

- Benefit from optimized compatibility with Autodesk and third-party solutions
- Analyze lighting scenarios with confidence
- Bring your design to life in a highly realistic way using 3D technology proven in the entertainment industry



Image courtesy of Homologue

Suit

Autodesk Design



Lynn Allen, *Cadalyst* columnist and worldwide Autodesk Technical Evangelist, speaks to more than 30,000 users each year. For the past fifteen years she has written a monthly column in *Cadalyst* magazine called "Circles and Lines" and is the voice behind *Cadalyst's* "Tips and Tricks Tuesdays". Lynn started using AutoCAD[®] software with Release 1.4, over 20 years ago, and got her start by teaching at the corporate and collegiate level for 12 years. A sought-after public speaker with a unique comedic style, Lynn has served as the Autodesk University emcee for ten years and is always one of the highest rated speakers. Her latest book is entitled *AutoCAD Professional Tips and Techniques*.

Cover: Image courtesy of Tait Towers, Inc.

Autodesk, AutoCAD, ATC, DWF, DWG, Inventor, ViewCube, ShowMotion, SketchBook, Showcase, and Mudbox are registered trademarks or trademarks of Autodesk, Inc., and/or its subsidiaries and/or affiliates in the USA and/or other countries. All other brand names, product names, or trademarks belong to their respective holders. Autodesk reserves the right to alter product and services offerings, and specifications and pricing at any time without notice, and is not responsible for typographical or graphical errors that may appear in this document.

© 2011 Autodesk, Inc. All rights reserved.

